ON SEPTEMBER 21, 2011 AND CAN ONLY BE CONSIDERED AS INDICATING THE GENERAL

INSTRUMENTATION FOR THIS SURVEY WAS A LEICA 1103 TOTAL STATION. PROCEDURES USED

IN THIS SURVEY WERE FIELD TRAVERSE, MEETING OR EXCEEDING STANDARDS SET BY WAC

CONDITIONS EXISTING AT THAT TIME.

332–130–090.

FIRE HYDRANT

WATER BLOW OFF

WATER VALVE

WATER VAULT

SANITARY SEWER CLEANOUT

STORM DRAIN MANHOLE

CATCH BASIN

CULVERT

TREE DECIDUOUS

LANDMARK TREE DECIDUOUS

TREE CONIFEROUS

LANDMARK TREE CONIFEROUS

TOPOGRAPHIC SURVEY INFORMATION CONTAINED ON THESE PLANS HAS

DEVELOPMENT CONSULTANTS, INC.) ASSUMES NO LIABILITY AS TO THE


BETWEEN WHAT IS SHOWN ON THE PLANS AND WHAT IS NOTED IN THE

FIELD SHOULD BE BROUGHT IMMEDIATELY TO THE ATTENTION OF THE

ACCURACY AND COMPLETENESS OF THIS DATA. ANY DISCREPANCIES FOUND

BEEN PROVIDED BY AXIS SURVEY & MAPPING. LDC, INC. (LAND

ENGINEER.



STORM:_

TRANS / ENGR:_

PLANNING DEPT:

Call 2 Business Days Before You Dig

Utilities Underground Location Center


(ID,MT,ND,OR,WA)


-800-424-5555


JURISDICTION: REDMON


DRAFTING BY: SCALE:

SHEET 1 OF 6









 \bigcirc

NW 1/4, NW 1/4 OF SEC 3, TWN 25 N, RGE 5 E, W.M., CITY OF REDMOND, KING COUNTY, WASHINGTON

ONSITE TREES

#	Tree Tag #	Species ID	DBH inches	Adj. DBH inches	Drip—line Radius feet	Health	Defects/Comments	Proposed Action						CRZ/TP Z/LOD				Tree Va
								Viable	Viable	Viable	Non- viable	Non-viable	Non-viable	Radius in feet	w	E	S	
								Retained	removed	Impacted	Remove	Impacted	retained			_		Not
1	1515	Black cottonwood	35	35	-	Poor	Butt swell, decay, carpenter ant, dead wood, lean				1							signific Landm
2	1520	Douglas fir	22	22	-	Poor	Wound on south side, abnormal bark, lost top, sloughing bark, red ring rot canker				1							Not signific
3	1521	Red alder	9	9	10	Good	T.O.S. Self-corrected lean, sloughing bark,		1									Signific
4	1522	Douglas fir	24	24	20	OK	dead branches, thin canopy Suppressed canopy tree, with open		1									Signific
5	1523	Western red cedar	28	28	-	Fair	wound with w 50% of trunk decay, carpenter ant frass				1							Not signific
6	1524	Douglas fir	19	19	-	Fair	Growing on a nurse log, free running sap, abnormal bark, epicormic root				1							Not signific
7	1525	Western red cedar	24	24	-	Poor	Little taper, decay at root crown, trunk rot, thin canopy, open wound, carpenter ants				1							Not signific
8	1526	Bigleaf maple	29, 26, 22, 19	24	_	Fair	Dead branches, decay in roots and trunk T.O.S.					1						Not signific
9	1527	Douglas fir	12	12	12	Fair	Dead wood, few branches, crack, canker — red ring rot					1						Not signific
10	1528	Bigleaf maple	26	26	20	OK	T.O.S. Abnormal bark, butt swell,			1				20	20	20	20	Signific
11	1529	Douglas fir	24	24	-	Fair	self-corrected lean at 20'				1							signific
12	1530	Bigleaf maple	18,7,20,18	16	-	Poor	Mostly hollow Nurse tree, large column of decay in				1							signific Not
13	1531	Bigleaf maple	40	40	-	Poor	scaffold				1							signific Landm Not
14	1532	Bigleaf maple	15, 13, 10	13	-	Poor	Nurse tree, large amount of decay 12'long crack from base, nurse tree,				1							signific
5	1533	Bigleaf maple	12	12	-	Poor	carpenter ant, woodpecker Large wound, carpenter ants,				1							signific
16	1534	Bigleaf maple	12	12	-	Poor	woodpecker				1							signific Not
7	1535	Bigleaf maple	15, 19	17	-	Poor	Mostly dead Buttress root rot, decay in trunk, dead				1							signific
8	1536	Bigleaf maple	10,12,8,8,12	10	-	Poor	branches, open wound, armillaria mycelia visible , carpenter ants				1							Not signific
9	1537	Bigleaf maple	16	16	-	Poor	Buttress root rot, trunk rot, dead branches, carpenter ants				1							No signific
0	1538	Bigleaf maple	10, 10, 10, 10	10	-	Poor	Root rot, trunk decay, dead wood, carpenter ant, woodpecker				1							No signifi
1	1539	Bigleaf maple	20	20	-	Poor	Root rot, trunk decay, carpenter ant, woodpecker				1							No signifi
2	1540	Bigleaf maple	10, 12, 5	12	-	Poor	Root rot, trunk rot, carpenter ant, one leader dead				1							No signifi
3	1541	Bigleaf maple	17	17	-	Poor	Nurse tree, lean, dead branches, trunk decay				1							No signifi
4	1542	Bigleaf maple	34	34	-	Poor	Abnormal bark, trunk decay, dead branches, Hypoxylon canker				1							No signifi No
5	1543	Bigleaf maple	12, 9, 9, 23	13	-	Poor	Decay at root collar, decay in trunk, dead branches, 2 leaders are dead				1							signifi Landn
6	1544	Western red cedar	20	20	22	OK	Growing on a nurse log, Low live crown ratio		1									Signifi
7	1545	Western red cedar	36	36	-	Poor	76" X 10" column of visible dead wood, carpenter ant, pileated woodpecker				1							No signific
8	1546	Douglas fir	20	20	-	Fair	Exposed roots, growing from nurse stump, abnormal bark, previous top failure, asymmetric canopy to south				1							No signifi
29	1547	Western red cedar	19	19	-	Poor	Conjoined base, exposed roots, 6' column of dead wood, carpenter ants,				1							No signific
60	1548	Western red cedar	42	42	25	Good	Two leaders fused together, with included bark, exposed roots, thin		1									Signifi Landr
31	1549	Douglas fir	32	32	_	Poor	canopy, slight lean to north Free running sap, canker, consistent				1							Not
	1550	Western red					with red ring rot Large column of dead wood				'							signific Not
32	1550	cedar	33	33	-	Fair					I							signific Landm Not
3	1551	Douglas fir	52	52	-	Poor	Decay, non-self-corrected lean, falling HAZARDOUS				1							signific Landm
34	1552	Western red cedar	33	33	-	Fair	Decay in buttress roots, shedding bark				1							Not signific Landm
55	1553	Douglas fir	36	36	33	Fair	Slight bulge at root crown, canker at 20', self—corrected lean, dead branches, lean, free flowing sap	1						33	33	33	33	Signific Landm
36	1554	Western red cedar	54	54	36	Fair	Decay in Buttress roots, thin crown,	1						36	36	36	36	Signific Landm
57	1555	Western red cedar	33	33	-	Dying	Very little live canopy, decay in buttress roots, carpenter ants						1					Not signific Landm
8	1556	Western red cedar	30	30	16	Dying	Dead branches, thin canopy, low live crown ratio						1	16	16	16	16	Not signific Landm
59	1557	Western red	12	12	8	Dying	Dead branches, thin canopy, low live						1	8	8	8	8	Not signific
10	1558	cedar Bigleaf maple	21, 18, 16, 14, 14, 10	16	20	OK	crown ratio Dead wood, moss	1						20	20	20	20	Landm
¥1	1559	Bigleaf maple	14, 14, 10	11	12	Fair	Large amount of decay at basal root	1						12	12	12	12	Signific
-2	1560	Bigleaf maple	11	11	15	OK	flare Dead scaffold, branches, T.O.S	1						15	15	15	15	Signific
3	1561	Bigleaf maple	13,13,16,15	14	20	OK	Trunks and scaffold decay T.O.S Multiple leaders with included bark,	1						20	20	20	20	Signifi
4	1562	Bigleaf maple Western red		18	20	OK _	decay T.O.S. Growing on a nurse log, column of		1					20	20	20	20	Signifi
5	1563	Western red cedar Western red	14	14	12	Poor	Growing on a nurse log, column of decay > 50% Girdled by barbed wire, growing on					1		12	12	12	12	signifi No
6	1564	cedar	16	16	12	Poor	nurse log, decay No taper, large cavity of decay, dead					1		12	12	12	12	signifi No
7	1565	Bigleaf maple	17	17	12	Fair Fair	wood 2 large cavities of decay at trunk flare					1		12	12	12	12 16	signifi Signifi

#	Tree Tag #	Species ID	DBH inches	Adj. DBH inches	Drip—line Radius feet	Health	Defects/Comments	Proposed Action					CRZ/TP Z/LOD				Tree Value
49	1568	Bigleaf maple	7, 21, 16, 19	16	25	Fair	Decay T.O.S could be pruned		1								Significant
50	1569	Bigleaf maple	17	17	12	OK	Low live crown ratio			1			12	12	12	12	Significant
51	1570	Bigleaf maple	12, 14, 10, 12	12	-	Poor	2 trunks dead				1						Not significant
52	1571	Bigleaf maple	9	9	-	Poor	Fell, Dead				1						Not significant
53	1572	Western red cedar	23	23	21	Good	Dead spur, exposed roots, thinning canopy			1			23	23	23	23	Significant
54	1573	Western red cedar	11	11	9	Fair	Large column of dead wood in trunk	1					9	9	9	9	Significant
55	1574	Bigleaf maple	14, 30, 16, 18, 23	20	-	Poor	T.O.S. but worse					1					Not significant
56	1575	Bigleaf maple	24, 23	24	-	Poor	Nurse tree, decay in trunk, roots, carpenter ants, dead wood					1					Not significant
57	1576	Bigleaf maple	22	22	-	Fair	Decay in buttress roots, ivy, co—dominant leaders with included bark				1						Not significant
58	1577	Bigleaf maple	34	34	-	Poor	No taper, no roots, included bark in leaders, split				1						Not significant
59	1578	Bigleaf maple	19, 7, 8, 19	13	-	Poor	Growing on a nurse log, log 2 of trunks are dead, self—corrected lean				1						Not significant
60	1579	Bigleaf maple	10,35,10,19,1 5,15,10,20,2 0	17	-	Poor	Growing as a nurse tree, too many leaders with included bark, dead wood in canopy				1						Not significant
61	1580	Bigleaf maple	23	23	-	Poor	Mostly dead, exposed roots, no taper, decay				1						Not significant
62	1581	Bigleaf maple	20, 11	16	-	Poor	Multiple failures, decay in trunk, dead wood				1						Not significant
63	1582	Bigleaf maple	12, 12	12	-	Poor	Exposed roots with decay, trunk decay, dead wood in canopy				1						Not significant
64	1583	Bigleaf maple	10	10	-	Fair	Not very much canopy, mostly trunk				1						Not significant
65	1584	Bigleaf maple	30, 26	28	14	Poor	Exposed roots with decay, trunk decay, dead wood					1	14	14	14	14	Not significant
66	1589	Black cottonwood	18, 21	20	15	OK	Co—dominant leaders at 3' with included bark		1								Significant
67	1590	Black cottonwood	21	21	18	Good	TOS		1								Significant

OFFSITE TREES

			T	I	T		T				I		I	ī
#	Tree Tag #	Species ID	DBH inches	Adj. DBH inches	Drip—line Radius feet	Health	Defects/Comments	Proposed Action			CRZ/TPZ/ LOD			
											Radius in feet			
								Retained	Impacted	Non- viable	N	W	Е	S
2	1495	Bigleaf maple	16, 16, 16, 16	16	18	Good	Split, some dead wood, Typical of species	1			18			
3	1496	Western red cedar	8	8	16	Good	Typical of species	1			10			
4	1497	Western red cedar	10	10	12	Good	Typical of species	1			14			
5	1498	Bigleaf maple	19, 20	20	15	Poor	Lost 1/2 of canopy		1		15			
6	1499	Douglas fir	Est. 20	20	15	Poor	Abnormal bark, few branches, trunk decay, sap Red ring rot		1		15			
7	1500	Douglas fir	Est. 24	24	20	Poor	Low live canopy ratio, dead branches, canker, sap, red ring rot		1		20			
8	1501	Bigleaf maple	21	21	15	Fair	Typical of species	1			21			
9	1502	Bigleaf maple	15	15	15	Poor	Root rot has destroyed nearly all the roots		1		15			
10	1503	Douglas fir	Est. 14	14	10	Poor	Suppressed canopy, butt, rot, abnormal bar, thin canopy		1		14			
11	1504	Western red cedar	22	22	20	Fair	Abnormal bark, base swell, wound, thin canopy		1		22			
12	1505	Western red cedar	Est. 12	12	12	Good	Remove dying spur	1			12			
13	1506	Douglas fir	26	26	18	Fair	Typical of species		1		18			
14	1507	Douglas fir	13"	13	-	Poor	Tree broken off at base and fallen onto 1506		1		_			
15	1508	Douglas fir	30	30	21	Fair	Butt swell, , bark beings to slough at base of tree, beetle damage in one buttress root, probable early root rot	1			21			
16	1509	Western red cedar	9, 14	12	15	Poor	Co-dominant leaders join at 3' with included bark		1		15			
17	1510	Douglas fir	22	22	15	Poor	Abnormal bark, lean to north, Laminated root rot conk		1		15			
18	1511	Bigleaf maple	12, 10, 6, 9	9	16	Poor	Hypoxylon infected		1		16			
19	1512	Douglas fir	35	35	18	Poor	Butt swell, crack, shedding bark, probable Laminated root rot		1		18			
20	1513	Douglas fir	14	14	18	Poor	Shedding popping bark, falling to north, large wound, dead wood, probable laminated root rot		1		18			
21	1514	Western red cedar	12	12	16	Poor	Large wound, swollen butt, self-correct lean		1		16			
22	1516	Black cottonwood	18	18	20	Poor	Trunk broken off at 30'		1		20			
23	1517	Black cottonwood	11, 11	11	15	Poor	Dead wood in canopy, co-dominant leaders, free flowing sap, leans toward site but canopy does not protrude over site		1		15			
24	1518	Black cottonwood	24	24	No canopy over this site	OK	Leans toward property slightly, dead wood in canopy,	1					-	
25	1519	Black cottonwood	36	36	-	Poor	Self-corrected lean, crack with decay, dead wood, woodpecker		1				_	
26	1567	Western red cedar	16	16	12	Fair	Nurse tree	1					15	
27	1585	Douglas fir	Est. 16	16	_	Poor	Lost top, bulge at base, early signs of laminated root rot		1					
28	1586	Bigleaf maple	Est.18	18	18	Good	Typical of species	1					18	
29	1587	Black cottonwood	Est. 16	16	15	Good	Typical of species	1					15	
30	A	Bigleaf maple	36 est.	36	_	Falling	Wet soil, causing tree to fall onto property		1					

Call 2 Business Days Before You Dig


1-800-424-5555

Utilities Underground Location Center
(ID,MT,ND,OR,WA)

THIS DEVELOPMENT SHALL BE CONSTRU OF REDMOND STANDARD SPECIFICATION	JCTED IN ACCORDANCE WITH THE 2014 CITY AND DETAILS.
APPROVED FOR CO	<u> ONSTRUCTION:</u>
FOR: DIRECTOR OF PUBLIC WORKS CITY OF REDMOND DATE: PLAN CHK ENGR: STORM: UTILITY: FIRE DEPT: TRANS / ENGR: PLANNING DEPT:	CONSTRUCTION AT ANY TIME THAT IS DISCOVERED THAT THE PROPOSED CONSTRUCTION DOES NOT OTHERWISE MEET THE APPLICABLE CONSTRUCTION STANDARDS. THE OWNER IS REQUIRED TO PROVIDE DESIGNS AND PLANS IN ACCORDANCE WITH APPLICABLE CITY STANDARDS AND ASSURES THAT CONSTRUCTION IS ACCOMPLISHED IN ACCORDANCE WITH THESE STANDARDS. THE OWNER AND/OR DESIGN ENGINEER AND/OR DESIGN ENGINEER AND/OR DESIGN ENGINEER AND/OR DESIGN ENGINEER AND/OR DESIGN

HEATHERS RIDGE SOUTH QUADRANT HOMES

710N




DRAWING NAME: 3171P-TP-0 DESIGNER: MWI
DRAFTING BY: RCF
DATE: 11-3-14
SCALE: AS NOTED
JURISDICTION: REDMOND

TR-02

SHEET 6 OF 6

By
Revisions
Revised per new site plan and City of
Redmond's comment letter dated 11/10/20
Revised per new site plan received 3-2-20
Revised per City's request letter dated
4-28-20



& Associates

Lar


UADRANT HOMES


APE PLAN HE


LANDSCAPE

Date
OCTOBER 2014
Scale
AS SHOWN
Drawn
BCL
Job
51-2014










STREE<u>T TREE PLANTING & STAKING D</u>ETAIL

NOT TO SCALE

NOTE:


ALL PLANTING BEDS AND LAWN AREAS ARE TO BE PREPARED AT MINIMUM PER CITY OF REDMOND STANDARD DETAIL NO. 632 "SOIL AMENDMENT AND DEPTH"



PLANTING NOTES


23 Whips Plant 24" O.C./ Native

- 1. Contractor shall be responsible for familiarizing themselves with the site improvements and existing site conditions prior to bidding and starting landscape work.
- 2. Contractor shall use caution while excavating to avoid disturbing any utilities encountered. Contractor is to promptly advise owner of any disturbed utilities. (Location service phone: 1-800-424-5555)
- 3. Contractor shall maintain and water all plant material for 1 year or until final inspection and acceptance
- 4. Contractor shall be responsible for computing specific quantities of ground covers and plant materials utilizing on-center spacing for plants as stated on the landscape plan and minimum planting distances as specified below in these notes.
- 5. Ground covers shall be planted in an equilateral triangular spacing pattern at the on center distances show on the plan or in the plant schedule. Where ground cover abuts curbing, sidewalks, signs or poles, minimum planting distances shall be 12" from center of plant to curb, sidewalk, etc. Minimum planting distance shall be 24" from center of trees and shrubs
- 6. Contractor shall be responsible for providing the quantities of plant that are represented by symbols on
- 7. Subgrade is to be within 1/10th of one foot as provided by contractor. All Planting areas to be cleared of all weeds, construction material, rocks, and sticks larger than 2" in diameter.
- 8. Scarify all compacted subgrades a minimum of 4". Apply a minimum 2" depth of compost to all lawn areas and 3" to all bed area then rototilled to a depth a 8". Than an additional 4"minimum of '3-Way' topsoil in all new lawn areas and 6" in new bed areas.
- Compost shall be the result of the biological degradation of Type 1 or 111 Feedstocks, under controlled conditions designed to promote aerobic decomposition per WAC 173-350-220, and meet the following criteria. Approved product meeting the specification:
- 1. Compost shall be certified in compliance with U.S. Composting Council Seal of Testing Assurance (STA) program.
- 2. Compost shall have an organic matter content of 35% to 65%
- 3. The carbon to nitrogen ratio shall be below 25:1. The carbon nitrogen ratio may be as high as 35:1 for planting composed entirely of plants native to the Puget Sound Lowlands region.
- 10. All beds and areas to receive a minimum of 3" "Fertil-mulch" mulch.
- 11. All plant material shall be fertilized with AGRO TRANSPLANT FERTILIZER 4-2-2 per manufactures recommendations.
- 12. All plant material shall conform to AAN STANDARDS FOR NURSERY STOCK, latest edition. Any replacements made at once.
 - A. General: All plant materials furnished shall be healthy representatives, typical of their species of variety and shall have a normal habit of growth. They shall be full, well branched, well proportioned, and have a vigorous, well developed root system. All plants shall be hardy under climatic conditions similar to those in the locality of the project.
 - B. Trees, shrubs, and groundcovers: Quantities, species, and varieties, sizes and conditions as shown on planting plan. Plants to be healthy, vigorous, well foliated when in leaf. Free of disease, injury, insects, decay, harmful defects, and all weeds. No substitutions shall be made without written approval from landscape architect or owner.
- 13. Contractor to provide a one-year warranty on all plant material.




SOLID CEDAR FENCE DETAIL

NOT TO SCALE



SPLIT-RAIL FENCE DETAIL


NOT TO SCALE




TIMBER CURBING DETAIL

Ecological Score Requirement

Longical Score Requirement	Points Awarded
25 percent of the plants installed are Northwest adaptive and 25% of the plants nstalled are native.	5 points
Minimum of 50 percent of required planting areas in disturbed soils are amended.	3 points
25% of the proposed trees are evergreen	5 points
25% of the landscape areas are designed with landscaping that does not irrigation will not required irrigation after three years.	3 points
Use of bioretention swales, engineered swales and or engineered wetlands that treats 25% of pollution generating impervious surfaces.	5 points
	Total Points 21







CERTIFICATE No. 375 ati

S

Ŋ

RD

~

ATHE


HOME **RANT** QUAD

Y Д

Date OCTOBER 2014 Scale AS NOTED AS SHOWN Drawn BCL

51 - 2014

SCALE I "=20'0"




PLANT SCHEDULE
BOTANICAL NAME COMMON NAME QTY SIZE COMMENTS


STREAM BUFFER MIGITATION PLANTINGS
Acer macrophylum Big Leaf Maple 2 2 gal. Full /Compact /Plant 10' O.C./ Native
Oemleria cerasiformis Indian Plum 4 2 gal. Full /Compact /Plant 5' O.C./ Native
Salix spp. Willow 23 Whips Plant 24" O.C./ Native

NORTH

Call before you Dig.


1-800-424-5555





CERTIFICATE No. 375

ne & Associate



HEATHERS RIDGE SOUTH

IGATION LANDSCAPE

Date
OCTOBER 2014
Scale
AS SHOWN
Drawn
BCL
Job
51-2014

